# **Operational Petrol Filling Station, Emilia Romagna, Northern Italy** In-Situ Chemical Oxidation and Bioremediation Treat TPH and BTEX





## **Summary**

Leakages from underground storage tanks (UST) at an operational petrol filling station located in a densely populated urban area in Northern Italy, resulted in significant TPH and BTEX contamination (with concentrations up to 1,000  $\mu$ g/L and 100  $\mu$ g/L respectively), impacting the soil and groundwater.

Contamination was migrating off-site and presenting an unacceptable risk to off-site receptors, resulting in a remediation requirement to reduce contaminant levels to below 350  $\mu$ g/L TPH and 1  $\mu$ g/L BTEX.

## **Application Design and Treatment**

The application design for the  $65m^2$  target area comprises of 8 injection points arranged in a 3 x 3 m grid spacing, which is being carried out over 2 phases. The first phase consists of the injection of RegenOx (oxidiser); the second of a further dose of RegenOx, followed by ORC-Advanced.

## **Regulatory Acceptance Despite Low Permeability Aquifer**

Upon injection into the subsurface, the In Situ Chemical Oxidation (ISCO) reagents are required to come into physical contact with the contaminant in order to cause the desired chemical reaction, and for this reason are typically applied to higher fluid volumes. Application can be challenging in low permeability formations.

Despite the extremely low permeability within the sites' sandy silt aquifer, our in-situ remedial approach proved the most appropriate remedial option, successfully gaining regulatory acceptance. Monitoring data show reductions in contaminant concentrations after treatment. Monitoring is still ongoing.

## **Remediation Details**

Site Type: Operational Petrol Station

REGENESIS

## Project Driver:

Posed unacceptable risk to human health

### **Remediation Approach:**

In-Situ Chemical Oxidation Enhanced Bioremediation

### **Technologies:**

RegenOx<sup>®</sup> , ORC-Advanced<sup>®</sup>

Geology		
	Bedrock	
	Gravel	
Х	Sand	
Х	Silt	
	Clay	

Medium		
Х	Groundwater	
	Saturated Soil	
	Vadose Zone	

сос	
Х	Petro HCs
	Petro LNAPL
	Chlorinated VOCs
	Metals

COC Concentration Levels: TPH - 1,000 μg/L BTEX - 100 μg/L

#### **Treatment Depth:**

1 m to 4 m BGL Volume Treated (m<sup>3</sup>): 65m<sup>2</sup> x 3 m = 195 m<sup>3</sup>

Remediation Cost: €25.000

#### © REGENESIS | www.regenesis.com